

Report No.: ENV/GCC/SIV/20-21/5-01  
Date : 18/03/2021

Order No.: Telecon  
Date :

Report Issued To: **GARGAON COLLEGE**  
Simaluguri, Sivasagar - 785686, Assam

### TEST RESULTS

Sample Ref. No.: GCC/2021/S-1203/01  
Collected On : 12-03-2021

Sample Source : College Playground  
Received On : 13-03-2021

Sample Type : Soil Sample  
Collected By : Envirocon Representative

Sl. No.	Parameters	Results
1.	pH of Water Extract	6.13
2.	% Carbon (dry wt.)	1.39
3.	% Nitrogen (dry wt.)	0.22
4.	Nitrogen & Organic Matter Status	Good
5.	Available K <sub>2</sub> O, ppm	141
6.	Available Potash Status	High
7.	Available Sulphur, ppm	32



*Deahata*  
Principal  
Gargaon College  
Simaluguri, Sivasagar (Assam)



Checked By: Mr. Pankaj Baroi, ENVIROCON

**NOTE:**

1. Results reported are valid at the time of and under the prevailing conditions of measurement.
2. Results refer only to the particular parameters tested.
3. This test report shall not be reproduced except in full, without the written permission of ENVIROCON, I.O.C.L (AOD) New Market, Digboi - 786171, Assam.

**Core Services:** Environmental Monitoring & Data Generation, EIA & EMP, Environmental Audit & Allied Environmental Management jobs  
**Associate Services:** Certification by Competent Person (CIP), NDT, Hydraulic Testing, Chartered Engineer Services etc.

Report No.: ENV/GGC/SIV/21-22/S-01  
Date : 23/03/2022

Order No.: Telecon  
Date :

Report Issued To : **GARGAON COLLEGE**  
Simaluguri, Sivasagar - 785686, Assam


### TEST RESULTS

Sample Ref. No. : GGC/2021/S-1503/01  
Collected On : 15-03-2022

Sample Source : College Playground  
Received On : 16-03-2022

Sample Type : Soil Sample  
Collected By : Envirocon Representative

Sl. No.	Parameters	Results
1.	pH of Water Extract	6.21
2.	% Carbon (dry wt.)	1.33
3.	% Nitrogen (dry wt.)	0.19
4.	Nitrogen & Organic Matter Status	Good
5.	Available K <sub>2</sub> O, ppm	137
6.	Available Potash Status	High
7.	Available Sulphur, ppm	35



*Dehata*  
Principal  
Gargaon College  
Simaluguri Sivasagar (Assam)



Checked By: Mr. Pankaj Baroi, **ENVIROCON**

- NOTE:**
1. Results reported are valid at the time of and under the prevailing conditions of measurement.
  2. Results refer only to the particular parameters tested.
  3. This test report shall not be reproduced except in full, without the written permission of ENVIROCON, I.O.C.L (AOD) New Market, Digboi - 786171, Assam.

**Core Services:** Environmental Monitoring & Data Generation, EIA & EMP, Environmental Audit & Allied Environmental Management jobs  
**Associate Services:** Certification by Competent Person (CIF), NDT, Hydraulic Testing, Chartered Engineer Services etc.